

Appendix A. Setup Photographs

<Conducted Emission>

<Original>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : A1 of A5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01

Report No.: FR650305D







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : A2 of A5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01



<Terminal>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : A3 of A5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01

Report No.: FR650305D







Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : A4 of A5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01




<Radiated Emission>

Y Plane

From 9 kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : A5 of A5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01

Report No.: FR650305D