


Appendix E. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : E1 of E6
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01







Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : E2 of E6
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01




<Radiated Emission>

Z Plane for CDD Modes with Ant. 1

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : E3 of E6
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: FR672014-01C




X Plane for CDD Modes with Ant. 2





HF




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : E4 of E6
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01




Z Plane for CDD Modes with MIMO Ant. 1+2

LF



HF




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : E5 of E6
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01




Z Plane for TXBF Modes with MIMO Ant. 1+2

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : E6 of E6
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01