


Appendix C. Setup Photographs

<Conducted Emission>

Mode 1

<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C1 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A








SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C2 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A



Mode 1



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C3 of C13 Report Issued Date: Oct. 07, 2016 Report Version : Rev. 03

Report No.: FR672834A







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C4 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No. : FR672834A



Mode 2
<Original test result with NFC antenna>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C5 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A



Report No.: FR672834A



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C6 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03



Mode 2
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C7 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C8 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A



Mode 3
<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C9 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A



Report No. : FR672834A




Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C10 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03



Mode 3
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C11 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C12 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03


Report No. : FR672834A




<Radiated Emission>

Z Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C13 of C13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834A