

Report No.: FR322304-07D


# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1



Mode 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A1 of A4 Report Issued Date : Aug. 14, 2013 : Rev. 01 Report Version





Report No.: FR322304-07D

## Mode 3



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A2 of A4
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01




## Report No.: FR322304-07D


## <Radiated Emission>

Y Plane

LF



## HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A3 of A4
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01






Report No. : FR322304-07D

## **Z** Plane

LF



#### HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A4 of A4
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01