


Report No.: FG010801

Appendix B. Setup Photographs

<Radiated Emission> WWAN Link Mode for Qwerty Keypad



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : B1 of B6
Report Issued Date : Mar. 08, 2010
Report Version : Rev. 01



Report No. : FG010801



Remote View

WWAN Link Mode for Numeric Keypad



Front View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : B2 of B6
Report Issued Date : Mar. 08, 2010
Report Version : Rev. 01



Report No.: FG010801



Rear View



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : B3 of B6
Report Issued Date : Mar. 08, 2010
Report Version : Rev. 01




Report No. : FG010801

Co-location with WLAN Mode for Qwerty Keypad



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : B4 of B6
Report Issued Date : Mar. 08, 2010
Report Version : Rev. 01



Report No. : FG010801



Remote View

Co-location with WLAN Mode for Numeric Keypad



Front View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : B5 of B6
Report Issued Date : Mar. 08, 2010
Report Version : Rev. 01



Report No.: FG010801



Rear View



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : B6 of B6
Report Issued Date : Mar. 08, 2010
Report Version : Rev. 01