

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : C1 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report No.: FR573017C

Report Template No.: BU5-FR15CWL Version 1.0




<Radiated Emission>

Z Plane for Sample 2

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : C2 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report No.: FR573017C

Report Template No.: BU5-FR15CWL Version 1.0



Z Plane for Sample 1

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : C3 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01


Report No.: FR573017C

Report Template No.: BU5-FR15CWL Version 1.0



Y Plane for Sample 3

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : C4 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0

Report No.: FR573017C