
3. **Internal Photograph of EUT**

Brand Name: MOTOROLA SOLUTIONS, INC. / Model Name: ATLS-T1B

Report No.: EP420805




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B

Page Number : 8 of 19 Report Issued Date : Jun. 10, 2014


Report Version : Rev. 01

Brand Name: MOTOROLA SOLUTIONS, INC. / Model Name: ATLS-T1B



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 9 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01


Brand Name: MOTOROLA SOLUTIONS, INC. / Model Name: ATLS-T1B



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 10 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01




Report No.: EP420805



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B


Page Number : 11 of 19 Report Issued Date : Jun. 10, 2014 Report Version : Rev. 01

Report No.: EP420805




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 12 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01

Report No.: EP420805



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 13 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01


Brand Name: MOTOROLA SOLUTIONS, INC. / Model Name: ATLS-T1B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 14 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01



Report No.: EP420805




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 15 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 16 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01

Report No.: EP420805




TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: UZ7ATLST1B
IC: 109AN-ATLST1B

Page Number : 17 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01




Report No.: EP420805



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B

Page Number : 18 of 19 Report Issued Date : Jun. 10, 2014 Report Version : Rev. 01

Report No.: EP420805



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ATLST1B IC: 109AN-ATLST1B Page Number : 19 of 19
Report Issued Date : Jun. 10, 2014
Report Version : Rev. 01