

Report No.: FR500915A

Appendix C. Setup Photographs

<Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS3678 Page Number : C1 of C3
Report Issued Date : May 04, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CBT Version 1.1







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS3678 Page Number : C2 of C3
Report Issued Date : May 04, 2016
Report Version : Rev. 02

Report No.: FR5O0915A


Report Template No.: BU5-FR15CBT Version 1.1




<Radiated Emission>

Y Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS3678 Page Number : C3 of C3
Report Issued Date : May 04, 2016
Report Version : Rev. 02

Report No.: FR5O0915A

Report Template No.: BU5-FR15CBT Version 1.1