Appendix B. Setup Photographs



## Report No. : FR010103A

## <Conducted Emission>

Mode 1



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B

: B1 of B7 Page Number Report Issued Date: Mar. 18, 2010 Report Version : Rev. 01



Report No.: FR010103A



Side View

## Mode 2




Front View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B2 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01



Report No.: FR010103A



Rear View



Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B3 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01





Mode 3

Front View





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B4 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: FR010103A





Report No.: FR010103A




Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B5 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01



## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B6 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: FR010103A



Report No. : FR010103A



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B7 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01