


Report No.: FR2D1407A

Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 Page Number : 1 of 2

Report Issued Date : Feb. 22, 2013 Report Version : Rev. 01



<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 Page Number : 2 of 2
Report Issued Date : Feb. 22, 2013

Report No.: FR2D1407A

Report Version : Rev. 01