

Appendix D. Product Photos


EUT with Qwerty Keypad



EUT with Numeric Keypad



Battery



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : D1 of D3
Report Issued Date : Feb. 22, 2010
Report Version : Rev. 01

Report No.: FA010801-05




FCC SAR Test Report

Holster 1



Holster 2




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : D2 of D3
Report Issued Date : Feb. 22, 2010
Report Version : Rev. 01

Report No.: FA010801-05



Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : D3 of D3
Report Issued Date : Feb. 22, 2010
Report Version : Rev. 01

Report No.: FA010801-05



Report No.: FA010801-05

Appendix E. Test Setup Photos



Right Cheek


Right Tilted






Left Cheek

Left Tilted








Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : E1 of E2
Report Issued Date : Feb. 22, 2010

Report Version : Rev. 01






DUT Keypad Up with Holster 1 with Phantom 0 cm Gap



Report No.: FA010801-05

DUT Keypad Up with Holster 2 with Phantom 0 cm Gap



DUT Keypad Down with Holster 2 with Phantom 0 cm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : E2 of E2
Report Issued Date : Feb. 22, 2010
Report Version : Rev. 01