

Appendix C. Product Photos

DUT with Battery 1 <1540mAh>

DUT with Battery 1 <1540mAh>

Report No.: HA010103B




DUT with Battery 2 <3080mAh>

DUT with Battery 2 <3080mAh>



Battery 1 <1540mAh>




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : C1 of C2
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01



FCC HAC T-Coil Test Report

Battery 2 <3080mAh>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : C2 of C2
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: HA010103B



Report No.: HA010103B


Appendix D. Test Setup Photos



Front View - Battery 1



Left Side View – Battery 1



Right Side View – Battery 1

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : D1 of D2 Report Issued Date : Mar. 18, 2010

Report Version : Rev. 01





Front View - Battery 2



Left Side View - Battery 2



Right Side View - Battery 2

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B

Page Number : D2 of D2 Report Issued Date: Mar. 18, 2010

Report No.: HA010103B

Report Version : Rev. 01