



Low Band Edge Plot on 802.11n (BW 20MHz) Channel 01 - Chain A+B(B)



Date: 8.NOV.2010 13:50:24




Date: 8.NOV.2010 13:50:31

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 241 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 20MHz) Channel 11 - Chain A



Date: 17.Nov.2010 17:24:11




Date: 17.Nov.2010 17:23:50

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 242 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 20MHz) Channel 11 - Chain B



Date: 1.NOV.2010 04:49:31




Date: 1.NOV.2010 04:49:25

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 243 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 20MHz) Channel 11 - Chain A+B(A)



Date: 8.NOV.2010 15:53:49




Date: 8.NOV.2010 15:53:43

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 244 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 20MHz) Channel 11 - Chain A+B(B)



Date: 8.NOV.2010 15:39:50



Date: 8.NOV.2010 15:39:43


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 245 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 16 and 22	Temperature :	25~27℃
Test Band :	802.11n (BW 40MHz)	Relative Humidity :	51~54%
Test Channel :	03 and 09	Test Engineer :	Ken Hsu


Low Band Edge Plot on 802.11n (BW 40MHz) Channel 03 - Chain A





Date: 10.NOV.2010 01:03:17

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 246 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02










Date: 10.NOV.2010 00:42:32

Low Band Edge Plot on 802.11n (BW 40MHz) Channel 03 - Chain B

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 247 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02


FCC RF Test Report




Date: 10.NOV.2010 01:15:24

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 248 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02





Date: 10.NOV.2010 01:14:50




Date: 10.NOV.2010 01:13:50


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 249 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Low Band Edge Plot on 802.11n (BW 40MHz) Channel 03 - Chain A+B(A)



Date: 10.NOV.2010 09:07:31




Date: 10.NOV.2010 09:07:53

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 250 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02





Date: 10.NOV.2010 09:08:15

Low Band Edge Plot on 802.11n (BW 40MHz) Channel 03 - Chain A+B(B)




Date: 10.NOV.2010 09:02:36


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 251 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02





Date: 10.NOV.2010 09:02:58




Date: 10.NOV.2010 09:03:20


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6



High Band Edge Plot on 802.11n (BW 40MHz) Channel 09 - Chain A



Date: 10.NOV.2010 00:56:28




Date: 10.NOV.2010 00:56:49

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 253 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 40MHz) Channel 09 - Chain B



Date: 10.NOV.2010 01:28:40




Date: 10.NOV.2010 01:29:02

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 254 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 40MHz) Channel 09 - Chain A+B(A)



Date: 8.NOV.2010 16:20:41




Date: 8.NOV.2010 16:21:03

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 255 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



High Band Edge Plot on 802.11n (BW 40MHz) Channel 09 - Chain A+B(B)



Date: 10.NOV.2010 09:32:15



Date: 10.NOV.2010 09:32:37


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 256 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 23 and 25	Temperature :	25~27℃
Test Band :	802.11a	Relative Humidity :	51~54%
Test Channel:	149 and 165	Test Engineer :	Ken Hsu

Low Band Edge Plot on 802.11a Channel 149 - Chain A




Date: 10.NOV.2010 02:01:23

Low Band Edge Plot on 802.11a Channel 149 - Chain B


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 257 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02





Date: 10.NOV.2010 02:32:52

Low Band Edge Plot on 802.11a Channel 149 - Chain A+B(A)




Date: 10.NOV.2010 10:21:21

Low Band Edge Plot on 802.11a Channel 149 - Chain A+B(B)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 258 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02


FCC RF Test Report




Date: 10.NOV.2010 10:16:16

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 259 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02






High Band Edge Plot on 802.11a Channel 165 - Chain A



Date: 10.NOV.2010 02:08:01

High Band Edge Plot on 802.11a Channel 165 - Chain B




Date: 10.NOV.2010 02:28:07

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 260 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




High Band Edge Plot on 802.11a Channel 165 - Chain A+B(A)



Date: 17.NOV.2010 07:49:14

High Band Edge Plot on 802.11a Channel 165 - Chain A+B(B)



Date: 17.Nov.2010 08:02:25


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 261 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 26 and 28	Temperature :	25~27℃
Test Band :	802.11n (BW 20MHz)	Relative Humidity :	51~54%
Test Channel :	149 and 165	Test Engineer :	Ken Hsu


Low Band Edge Plot on 802.11n (BW 20MHz) Channel 149 - Chain A



Date: 10.NOV.2010 03:13:42


Low Band Edge Plot on 802.11n (BW 20MHz) Channel 149 - Chain B

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 262 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Date: 10.NOV.2010 02:49:24

Low Band Edge Plot on 802.11n (BW 20MHz) Channel 149 - Chain A+B(A)




Date: 17.NOV.2010 10:21:26

Low Band Edge Plot on 802.11n (BW 20MHz) Channel 149 - Chain A+B(B)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 263 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report




Date: 17.NOV.2010 09:09:21

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 264 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




High Band Edge Plot on 802.11n (BW 20MHz) Channel 165 - Chain A



Date: 10.NOV.2010 03:08:27

High Band Edge Plot on 802.11n (BW 20MHz) Channel 165 - Chain B




Date: 10.NOV.2010 02:54:03

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 265 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




High Band Edge Plot on 802.11n (BW 20MHz) Channel 165 - Chain A+B(A)



Date: 17.NOV.2010 10:02:26

High Band Edge Plot on 802.11n (BW 20MHz) Channel 165 - Chain A+B(B)



Date: 17.NOV.2010 09:06:46


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 266 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 29 and 30	Temperature :	25~27 ℃
Test Band :	802.11n (BW 40MHz)	Relative Humidity :	51~54%
Test Channel :	151 and 159	Test Engineer :	Ken Hsu

Low Band Edge Plot on 802.11n (BW 40MHz) Channel 151 - Chain A




Date: 10.NOV.2010 03:27:13

Low Band Edge Plot on 802.11n (BW 40MHz) Channel 151 - Chain B


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 267 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report



Date: 19.NOV.2010 13:47:46

Low Band Edge Plot on 802.11n (BW 40MHz) Channel 151 - Chain A+B(A)




Date: 17.NOV.2010 10:26:45

Low Band Edge Plot on 802.11n (BW 40MHz) Channel 151 - Chain A+B(B)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 268 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report




Date: 17.NOV.2010 12:34:14

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 269 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




High Band Edge Plot on 802.11n (BW 40MHz) Channel 159 - Chain A



Date: 10.NOV.2010 03:29:33

High Band Edge Plot on 802.11n (BW 40MHz) Channel 159 - Chain B




Date: 10.NOV.2010 03:40:43

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 270 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




High Band Edge Plot on 802.11n (BW 40MHz) Channel 159 -



Date: 17.NOV.2010 10:40:44

High Band Edge Plot on 802.11n (BW 40MHz) Channel 159 - Chain A+B(B)



Date: 17.NOV.2010 10:59:19

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 271 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



3.4 Spurious Emission Measurement

3.4.1 Limit of Spurious Emission Measurement

All harmonics/spurs must be at least 20 dB down from the highest emission level within the authorized band.


3.4.2 Measuring Instruments

See list of measuring instruments of this test report.

3.4.3 Test Procedure

- 1. The transmitter output was connected to the spectrum analyzer via a low lose cable.
- 2. Set RBW = 100 kHz, Video bandwidth (VBW) > RBW, scan up through 10th harmonic. All harmonics/spurs must be at least 20 dB down from the highest emission level within the authorized band as measured with a 100 kHz RBW.

3.4.4 Test Setup



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 272 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



3.4.5 Test Result


Test Mode :	Mode 1~5	Temperature :	25~27℃
Test Band :	802.11b	Relative Humidity :	51~54%
Test Channel :	01, 02, 06, 10, 11	Test Engineer :	Ken Hsu

Conducted Spurious Emission Plot on 802.11b Channel 01 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 01:53:15

Conducted Spurious Emission Plot on 802.11b Channel 01 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 01:53:32

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 273 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 01 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 01:41:51

Conducted Spurious Emission Plot on 802.11b Channel 01 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 01:26:46

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 274 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 01 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 13:21:37

Conducted Spurious Emission Plot on 802.11b Channel 01 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 13:19:43

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 275 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 01 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 13:17:36

Conducted Spurious Emission Plot on 802.11b Channel 01 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 13:16:08

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 276 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 02 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 02:01:04

Conducted Spurious Emission Plot on 802.11b Channel 02 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 02:01:20

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 277 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 02 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 01:45:56

Conducted Spurious Emission Plot on 802.11b Channel 02 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 01:27:46

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 278 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 02 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 13:10:20

Conducted Spurious Emission Plot on 802.11b Channel 02 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 13:09:09

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 279 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 02 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 13:14:29

Conducted Spurious Emission Plot on 802.11b Channel 02 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 13:12:51

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 280 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 06



Date: 9.NOV.2010 02:02:39

Conducted Spurious Emission Plot on 802.11b Channel 06 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 02:02:56

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 281 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 06 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 01:28:41

Conducted Spurious Emission Plot on 802.11b Channel 06 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 01:28:58

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 282 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 06



Date: 8.NOV.2010 13:05:24

Conducted Spurious Emission Plot on 802.11b Channel 06 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 13:04:04

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 283 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 06 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 13:00:47

Conducted Spurious Emission Plot on 802.11b Channel 06 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 12:56:12

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 284 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 10 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 02:03:46

Conducted Spurious Emission Plot on 802.11b Channel 10 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 02:04:03

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 285 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 10



Date: 9.NOV.2010 01:31:01

Conducted Spurious Emission Plot on 802.11b Channel 10 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 01:31:17

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 286 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 10 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 12:52:21

Conducted Spurious Emission Plot on 802.11b Channel 10 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 12:52:38

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 287 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 10 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 12:54:01

Conducted Spurious Emission Plot on 802.11b Channel 10 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 12:54:18

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 288 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 11 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 02:04:45

Conducted Spurious Emission Plot on 802.11b Channel 11 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 02:05:02

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 289 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 11 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 01:34:03

Conducted Spurious Emission Plot on 802.11b Channel 11 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 01:34:19

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 290 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 11 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 12:51:06

Conducted Spurious Emission Plot on 802.11b Channel 11 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 12:51:22

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 291 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11b Channel 11 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 12:46:59

Conducted Spurious Emission Plot on 802.11b Channel 11 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 12:47:16

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 292 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 6~10	Temperature :	25~27 ℃
Test Band :	802.11g	Relative Humidity :	51~54%
Test Channel :	01, 02, 06, 10, 11	Test Engineer :	Ken Hsu


Conducted Spurious Emission Plot on 802.11g Channel 01 between 30 MHz~3 GHz - Chain A



Date: 1.NOV.2010 02:49:39


Conducted Spurious Emission Plot on 802.11g Channel 01 between 1 GHz~25 GHz - Chain A

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 293 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Date: 1.NOV.2010 02:49:56

Conducted Spurious Emission Plot on 802.11g Channel 01 between 30 MHz~3 GHz - Chain B




Date: 17.NOV.2010 18:11:16

Conducted Spurious Emission Plot on 802.11g Channel 01 between 1 GHz~25 GHz - Chain B

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 294 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report




Date: 17.NOV.2010 18:11:33

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 295 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 01 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 09:30:35

Conducted Spurious Emission Plot on 802.11g Channel 01 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 09:30:52

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 296 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 01 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 09:46:34

Conducted Spurious Emission Plot on 802.11g Channel 01 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 09:46:50

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 297 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 02 between 30 MHz~3 GHz - Chain A



Date: 1.NOV.2010 03:01:39

Conducted Spurious Emission Plot on 802.11g Channel 02 between 1 GHz~25 GHz - Chain A




Date: 1.NOV.2010 03:01:56

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 298 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 02 between 30 MHz~3 GHz - Chain B



Date: 17.NOV.2010 18:32:00

Conducted Spurious Emission Plot on 802.11g Channel 02 between 1 GHz~25 GHz - Chain B




Date: 17.NOV.2010 18:32:17

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 299 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 02 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 10:14:42

Conducted Spurious Emission Plot on 802.11g Channel 02 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 10:14:59

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 300 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 02 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 10:00:14

Conducted Spurious Emission Plot on 802.11g Channel 02 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 10:00:31

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 301 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 06 between 30 MHz~3 GHz - Chain A



Date: 1.NOV.2010 03:14:41

Conducted Spurious Emission Plot on 802.11g Channel 06 between 1 GHz~25 GHz - Chain A




Date: 1.NOV.2010 03:14:58

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 302 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 06 between 30 MHz~3 GHz - Chain B



Date: 17.NOV.2010 18:36:42

Conducted Spurious Emission Plot on 802.11g Channel 06 between 1 GHz~25 GHz - Chain B




Date: 17.NOV.2010 18:36:59

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 303 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 06 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 10:27:05

Conducted Spurious Emission Plot on 802.11g Channel 06 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 10:27:22

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 304 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 06 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 10:40:08

Conducted Spurious Emission Plot on 802.11g Channel 06 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 10:40:30

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 305 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 10 between 30 MHz~3 GHz - Chain A



Date: 1.NOV.2010 03:29:11

Conducted Spurious Emission Plot on 802.11g Channel 10 between 1 GHz~25 GHz - Chain A




Date: 1.NOV.2010 03:29:27

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6




Conducted Spurious Emission Plot on 802.11g Channel 10 between 30 MHz~3 GHz - Chain B



Date: 17.NOV.2010 18:48:11

Conducted Spurious Emission Plot on 802.11g Channel 10 between 1 GHz~25 GHz - Chain B




Date: 17.NOV.2010 18:48:27

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 307 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 10 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 11:25:51

Conducted Spurious Emission Plot on 802.11g Channel 10 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 11:26:08

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 308 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 10 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 10:52:53

Conducted Spurious Emission Plot on 802.11g Channel 10 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 10:53:10

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 309 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 11 between 30 MHz~3 GHz - Chain A



Date: 1.NOV.2010 03:43:47

Conducted Spurious Emission Plot on 802.11g Channel 11 between 1 GHz~25 GHz - Chain A




Date: 1.NOV.2010 03:44:04

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 310 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 11



Date: 17.NOV.2010 19:01:15

Conducted Spurious Emission Plot on 802.11g Channel 11 between 1 GHz~25 GHz - Chain B




Date: 17.NOV.2010 19:01:32

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 311 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 11 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 12:30:44

Conducted Spurious Emission Plot on 802.11g Channel 11 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 12:31:00

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 312 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11g Channel 11 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 12:45:00

Conducted Spurious Emission Plot on 802.11g Channel 11 between 1 GHz~25 GHz - Chain A+B(B)



Date: 8.NOV.2010 12:45:17


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 313 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 11~15	Temperature :	25~27℃
Test Band :	802.11n (BW 20MHz)	Relative Humidity :	51~54%
Test Channel :	01, 02, 06, 10, 11	Test Engineer :	Ken Hsu

Conducted Spurious Emission Plot on 802.11n (BW 20MHz)

Channel 01 between 30 MHz~3 GHz - Chain A




Date: 17.NOV.2010 16:30:05

Conducted Spurious Emission Plot on 802.11n (BW 20MHz)
Channel 01 between 1 GHz~25 GHz - Chain A


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 314 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report



Date: 17.NOV.2010 16:30:22

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 01 between 30 MHz~3 GHz - Chain B




Date: 1.NOV.2010 03:58:08

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 01 between 1 GHz~25 GHz - Chain B

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 315 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report




Date: 1.NOV.2010 03:58:25

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 316 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 01 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 14:01:14

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 01 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 14:01:31

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 317 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 01 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 13:46:49

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 01 between 1 GHz~25 GHz - Chain A+B(B)





Date: 8.NOV.2010 13:47:07

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 318 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02








Date: 17.NOV.2010 16:42:34

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 1 GHz~25 GHz - Chain A




Date: 17.NOV.2010 16:42:51

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 319 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 30 MHz~3 GHz - Chain B



Date: 1.NOV.2010 04:10:07

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 1 GHz~25 GHz - Chain B




Date: 1.NOV.2010 04:10:24

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 320 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 14:16:57

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 14:17:14

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 14:30:14

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 02 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 14:30:31

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 322 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 06 between 30 MHz~3 GHz - Chain A



Date: 17.NOV.2010 16:56:44

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 06 between 1 GHz~25 GHz - Chain A




Date: 17.NOV.2010 16:57:00

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 323 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz)



Date: 1.NOV.2010 04:21:39

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 06 between 1 GHz~25 GHz - Chain B




Date: 1.NOV.2010 04:21:56

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 324 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz)



Date: 8.NOV.2010 15:00:41

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 06 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 15:00:58

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 06 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 14:43:35

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 06 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 14:43:52

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 326 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz)



Date: 17.NOV.2010 17:08:52

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 1 GHz~25 GHz - Chain A




Date: 17.NOV.2010 17:09:08

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 327 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 30 MHz~3 GHz - Chain B



Date: 1.NOV.2010 04:35:37

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 1 GHz~25 GHz - Chain B




Date: 1.NOV.2010 04:35:53

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 328 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 15:13:27

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 15:13:44

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 329 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 30 MHz~3 GHz - Chain A+B(B)



Date: 8.NOV.2010 15:35:21

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 10 between 1 GHz~25 GHz - Chain A+B(B)




Date: 8.NOV.2010 15:35:38

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 330 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 30 MHz~3 GHz - Chain A



Date: 17.NOV.2010 17:24:58

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 1 GHz~25 GHz - Chain A




Date: 17.NOV.2010 17:25:15

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 331 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 30 MHz~3 GHz - Chain B



Date: 1.NOV.2010 04:50:10

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 1 GHz~25 GHz - Chain B




Date: 1.NOV.2010 04:50:27

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 332 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 30 MHz~3 GHz - Chain A+B(A)



Date: 8.NOV.2010 16:07:43

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 1 GHz~25 GHz - Chain A+B(A)




Date: 8.NOV.2010 16:03:48

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 333 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 20MHz)



Date: 8.NOV.2010 15:49:58

Conducted Spurious Emission Plot on 802.11n (BW 20MHz) Channel 11 between 1 GHz~25 GHz - Chain A+B(B)



Date: 8.NOV.2010 15:50:15


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 334 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02



Test Mode :	Mode 16~22	Temperature :	25~27 ℃
Test Band :	802.11n (BW 40MHz)	Relative Humidity :	51~54%
Test Channel :	03, 04, 05, 06, 07, 08, 09	Test Engineer :	Ken Hsu

Conducted Spurious Emission Plot on 802.11n (BW 40MHz)

Channel 03 between 30 MHz~3 GHz - Chain A




Date: 9.NOV.2010 04:34:28

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 1 GHz~25 GHz - Chain A


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 335 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report



Date: 9.NOV.2010 04:32:03

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 30 MHz~3 GHz - Chain B




Date: 9.NOV.2010 04:16:23

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 1 GHz~25 GHz - Chain B

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 336 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02

FCC RF Test Report




Date: 9.NOV.2010 03:42:44

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 337 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 30 MHz~3 GHz - Chain A+B(A)



Date: 9.NOV.2010 20:14:54

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 1 GHz~25 GHz - Chain A+B(A)




Date: 9.NOV.2010 20:15:11

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 338 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 30 MHz~3 GHz - Chain A+B(B)



Date: 10.NOV.2010 08:12:52

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 03 between 1 GHz~25 GHz - Chain A+B(B)




Date: 10.NOV.2010 08:13:08

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 339 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 05:16:16

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 04:38:06

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 340 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 04:17:37

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 03:41:27

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 341 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 30 MHz~3 GHz - Chain A+B(A)



Date: 9.NOV.2010 19:52:30

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 1 GHz~25 GHz - Chain A+B(A)




Date: 9.NOV.2010 19:52:46

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 342 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz)



Date: 9.NOV.2010 18:52:39

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 04 between 1 GHz~25 GHz - Chain A+B(B)




Date: 9.NOV.2010 18:52:56

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 343 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 05:15:07

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 04:42:12

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 344 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 30 MHz~3 GHz - Chain B



Date: 10.NOV.2010 01:06:25

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 03:28:22

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 345 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 30 MHz~3 GHz - Chain A+B(A)



Date: 9.NOV.2010 18:30:51

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 1 GHz~25 GHz - Chain A+B(A)




Date: 9.NOV.2010 18:31:08

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 346 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz)



Date: 9.NOV.2010 18:50:27

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 05 between 1 GHz~25 GHz - Chain A+B(B)




Date: 9.NOV.2010 18:50:43

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 347 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 05:13:52

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 04:45:08

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 348 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 04:07:23

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 03:31:33

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 349 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 30 MHz~3 GHz - Chain A+B(A)



Date: 10.NOV.2010 09:21:47

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 1 GHz~25 GHz - Chain A+B(A)




Date: 10.NOV.2010 09:22:03

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 350 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 30 MHz~3 GHz - Chain A+B(B)



Date: 10.NOV.2010 09:27:53

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 06 between 1 GHz~25 GHz - Chain A+B(B)




Date: 10.NOV.2010 09:28:09

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 351 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 05:06:59

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 04:48:33

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 352 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 04:08:57

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 03:34:08

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 353 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz)



Date: 10.NOV.2010 09:22:50

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 1 GHz~25 GHz - Chain A+B(A)




Date: 10.NOV.2010 09:23:07

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 354 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 30 MHz~3 GHz - Chain A+B(B)



Date: 10.NOV.2010 09:26:56

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 07 between 1 GHz~25 GHz - Chain A+B(B)



Date: 10.NOV.2010 09:27:13


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 355 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz)





Date: 9.NOV.2010 05:05:08

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 1 GHz~25 GHz - Chain A




Date: 9.NOV.2010 04:51:37

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 356 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 30 MHz~3 GHz - Chain B



Date: 9.NOV.2010 04:09:51

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 1 GHz~25 GHz - Chain B




Date: 9.NOV.2010 03:36:58

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 357 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 30 MHz~3 GHz - Chain A+B(A)



Date: 10.NOV.2010 09:24:28

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 1 GHz~25 GHz - Chain A+B(A)




Date: 10.NOV.2010 09:24:44

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 358 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 30 MHz~3 GHz - Chain A+B(B)



Date: 10.NOV.2010 09:26:04

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 08 between 1 GHz~25 GHz - Chain A+B(B)




Date: 10.NOV.2010 09:26:21

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 359 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02




Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 09 between 30 MHz~3 GHz - Chain A



Date: 9.NOV.2010 05:03:16

Conducted Spurious Emission Plot on 802.11n (BW 40MHz) Channel 09 between 1 GHz~25 GHz - Chain A



Date: 9.NOV.2010 04:55:12

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 360 of 480
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 02