

Report No.: FR322304-07A

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A1 of A3
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01



Report No.: FR322304-07A

Mode 2



Mode 3



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A2 of A3
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01




<Radiated Emission>

<Y Plane>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A3 of A3
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01

Report No.: FR322304-07A