


Appendix D. Setup Photographs

<Radiated Emission>

Antenna 6 for 4.5V



LF

HF

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D1 of D12
Report Issued Date : Oct. 30, 2012
Report Version : Rev. 01

Report No.: FR290603A





Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D2 of D12 Report Issued Date : Oct. 30, 2012






Antenna 6 for 3.3V

LF





HF

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : D3 of D12 Report Issued Date: Oct. 30, 2012

Report No.: FR290603A



Front View





Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D4 of D12 Report Issued Date : Oct. 30, 2012






Antenna 7 for 4.5V

LF





HF

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : D5 of D12 Report Issued Date: Oct. 30, 2012

Report No.: FR290603A





Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D6 of D12
Report Issued Date : Oct. 30, 2012
Report Version : Rev. 01






Antenna 7 for 3.3V







HF

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : D7 of D12 Report Issued Date: Oct. 30, 2012 Report Version : Rev. 01

Report No.: FR290603A





Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D8 of D12 Report Issued Date : Oct. 30, 2012






Antenna 8 for 4.5V

LF





HF

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : D9 of D12 Report Issued Date: Oct. 30, 2012

Report No.: FR290603A





Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D10 of D12 Report Issued Date : Oct. 30, 2012 Report Version : Rev. 01






Antenna 8 for 3.3V

LF





HF

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D11 of D12 Report Issued Date : Oct. 30, 2012

Report No.: FR290603A





Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : D12 of D12 Report Issued Date : Oct. 30, 2012 Report Version : Rev. 01