

Appendix B. Setup Photographs

<Conducted Emission> Mode 1



Front View




Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B1 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: FR010103C





Side View

Mode 2



Front View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B2 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01





Rear View





Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B3 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01





Mode 3

Front View





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B4 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: FR010103C







Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B5 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01





<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B6 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01





Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B Page Number : B7 of B7
Report Issued Date : Mar. 18, 2010
Report Version : Rev. 01