Appendix D. Antenna Location & SAR Test Setup Photos



Report No. :FA782919

RFID Antenna Location





Top Side View (RFID terminal)



Top Side View (RFID terminal with WLAN/BT terminal)



Right Side View (RFID terminal)



Right Side View (RFID terminal with WLAN/BT terminal)



Left Side View (RFID terminal)

Left Side View (RFID terminal with WLAN/BT terminal)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

Issued Date: Oct. 20, 2017 Form version.: 170509 FCC ID: UZ7RFD2000 Page D2 of D3







Left Side, Test Separation 0 mm





Top side, Test Separation 0 mm



Bottom Side, Test Separation 0 mm

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

Issued Date: Oct. 20, 2017 Form version. : 170509 FCC ID: UZ7RFD2000 Page D3 of D3