


Appendix E. Setup Photographs

<Conducted Emission>

Mode 1

<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E1 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E2 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B



Mode 1
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E3 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E4 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B



Mode 2
<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E5 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E6 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B



Mode 2
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E7 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B








SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E8 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B



Mode 3
<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E9 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E10 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B



Mode 3
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E11 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E12 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01


Report No.: FR672834B



<Radiated Emission>

Z Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : E13 of E13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834B