



Report No.: FA320416

Appendix D. SAR Test Setup Photos



Right Cheek

Right Tilted




Left Cheek Left Tilted

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67ND Page Number : D1 of D2
Report Issued Date : Apr. 02, 2013

Report Version : Rev. 01







1.5cm Timburhuduni

Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap



Front of the DUT with Phantom 0 cm Gap (DUT with Soft Holster)



Front of the DUT with Phantom 0 cm Gap (DUT with Rigid Holster)

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67ND Page Number : D2 of D2 Report Issued Date: Apr. 02, 2013 Report Version : Rev. 01