

Appendix E. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E1 of E4
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01

Report No.: FR650305E



Report No.: FR650305E



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E2 of E4
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01




Report No.: FR650305E


<Radiated Emission>

X Plane for Non-TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E3 of E4
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01



Report No.: FR650305E

X Plane for TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E4 of E4
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01