

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : B1 of B4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01


Report No.: FR573017A



<Radiated Emission>

Y Plane for Sample 2

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : B2 of B4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report No.: FR573017A



Y Plane for Sample 1

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : B3 of B4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01


Report No.: FR573017A



Report No.: FR573017A

Y Plane for Sample 3

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : B4 of B4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01