


Appendix A. Setup Photographs

<Conducted Emission>

<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : A1 of A5
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2

Report No.: FR672014-01D







Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : A2 of A5
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01



Report No.: FR672014-01D

<Terminal test result with dummy load>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : A3 of A5
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01



Report No.: FR672014-01D



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : A4 of A5
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01




Report No.: FR672014-01D

<Radiated Emission>

Z Plane

From 9kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K Page Number : A5 of A5
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01