

# Appendix C. Setup Photographs

### <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80N0 Page Number : C1 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report No.: FR573018C




## Report Report No. : FR573018C

#### <Radiated Emission>

Y Plane for Sample 1

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80N0 Page Number : C2 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01




Report No.: FR573018C

#### **Z Plane for Sample 2**

LF



HF




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80N0 Page Number : C3 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01




#### **Z Plane for Sample 3**

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80N0 Page Number : C4 of C4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report No.: FR573018C