

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : A1 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0

Report No.: FR661812D





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : A2 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812D

Report Template No.: BU5-FR15CNFC Version 1.0



Mode 2



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : A3 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0

Report No.: FR661812D





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : A4 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812D

Report Template No.: BU5-FR15CNFC Version 1.0




<Radiated Emission>

<Z Plane>

From 9kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : A5 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0

Report No.: FR661812D