


Report No.: 441804-22

Photographs of EUT

Model No.: AP-7522








Report No.: 441804-22





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 2 OF 5
ISSUED DATE : Oct. 08, 2015











Report No.: 441804-22

Adapter

Model No.:

NU60-H120500-13





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 4 OF 5
ISSUED DATE : Oct. 08, 2015




Report No.: 441804-22





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 5 OF 5

ISSUED DATE : Oct. 08, 2015






Photographs of EUT

Ant. 1






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 1 OF 16
ISSUED DATE : Oct. 08, 2015








Ant. 2













PAGE NUMBER : 3 OF 16
ISSUED DATE : Oct. 08, 2015










Ant. 3
















Ant. 4






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 6 OF 16
ISSUED DATE : Oct. 08, 2015










SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 7 OF 16
ISSUED DATE : Oct. 08, 2015






Ant. 5






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 8 OF 16
ISSUED DATE : Oct. 08, 2015








Ant. 6













PAGE NUMBER : 10 OF 16
ISSUED DATE : Oct. 08, 2015






Ant. 7





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 11 OF 16
ISSUED DATE : Oct. 08, 2015










PAGE NUMBER : 12 OF 16
ISSUED DATE : Oct. 08, 2015








Ant. 8




SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 13 OF 16 ISSUED DATE : Oct. 08, 2015













Ant. 9





