

Report No. : FA010801

Appendix D. Product Photos


EUT with Qwerty Keypad



EUT with Numeric Keypad



Battery




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : D1 of D3
Report Issued Date : Mar. 26, 2010
Report Version : Rev. 03





Holster 1



Holster 2




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : D2 of D3
Report Issued Date : Mar. 26, 2010
Report Version : Rev. 03

Report No.: FA010801



Report No. : FA010801

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : D3 of D3
Report Issued Date : Mar. 26, 2010
Report Version : Rev. 03



Report No. : FA010801

Appendix E. Test Setup Photos



Right Cheek

Right Tilted






Left Cheek

Left Tilted








Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : E1 of E2
Report Issued Date : Mar. 26, 2010
Report Version : Rev. 03






DUT Keypad Up with Holster 1 with Phantom 0 cm Gap



DUT Keypad Up with Holster 2 with Phantom 0 cm Gap



DUT Keypad Down with Holster 2 with Phantom 0 cm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC659B Page Number : E2 of E2
Report Issued Date : Mar. 26, 2010
Report Version : Rev. 03