

## 2. Internal Photograph of EUT

Brand Name: Motorola / Model Name: AP-6

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 4 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 5 of 32 Report Issued Date : Dec. 09, 2010

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 6 of 32 Report Issued Date : Dec. 09, 2010

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 7 of 32 Report Issued Date : Dec. 09, 2010







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 8 of 32 Report Issued Date : Dec. 09, 2010


Report No.: EP092308



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 9 of 32 Report Issued Date : Dec. 09, 2010

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 10 of 32 Report Issued Date : Dec. 09, 2010

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 11 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 12 of 32

Report Issued Date : Dec. 09, 2010

Report Version

: Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 13 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 14 of 32 Report Issued Date : Dec. 09, 2010

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 15 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 16 of 32 Report Issued Date : Dec. 09, 2010

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 17 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 18 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 19 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 20 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 21 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 22 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 23 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 24 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number

: 25 of 32 Report Issued Date : Dec. 09, 2010

Report Version

: Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number Report Issued Date : Dec. 09, 2010


: 26 of 32

Report Version

: Rev. 01



Report No.: EP092308




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 27 of 32 Report Issued Date : Dec. 09, 2010 Report Version : Rev. 01




Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 28 of 32
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01



Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 29 of 32 Report Issued Date : Dec. 09, 2010 Report Version : Rev. 01

Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 30 of 32
Report Issued Date : Dec. 09, 2010

Report No.: EP092308




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 31 of 32

Report Issued Date : Dec. 09, 2010



Report No.: EP092308



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 32 of 32 Report Issued Date : Dec. 09, 2010 Report Version : Rev. 01