

Appendix A. Setup Photographs

<Conducted Emission> <Original>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : A1 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR660115D





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : A2 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR660115D



Report No.: FR660115D

<Terminal>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : A3 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : A4 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR660115D



Report No.: FR660115D

<Radiated Emission>

Z Plane

From 9 kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : A5 of A5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01