

Report No. : FR541789

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7USB1 Page Number : B1 of B2
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 03

Report Template No.: BU5-FR15CBT4.0 Version 1.0



## <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7USB1 Page Number : B2 of B2
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 03

**Report No.: FR541789** 

Report Template No.: BU5-FR15CBT4.0 Version 1.0