
## **Appendix E. Setup Photographs**

## <Conducted Emission>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTBRDGM Page Number : E1 of E3
Report Issued Date : Dec. 09, 2016
Report Version : Rev. 01

Report No.: FR6O0724C

Report Template No.: BU5-FR15EWL Version 1.4





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTBRDGM Page Number : E2 of E3
Report Issued Date : Dec. 09, 2016

Report No.: FR6O0724C

Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.4

## CC Test Report No.: FR600724C


## <Radiated Emission>

Y Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTBRDGM Page Number : E3 of E3
Report Issued Date : Dec. 09, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.4