


Appendix D. Test Setup Photos

<Battery 1 with Scanner>



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : D1 of D1 Report Issued Date : Aug. 14, 2013


Report No.: HA322304-07A

Report Version : Rev. 01



Report No.: HA322304-07A


<Battery 1 without Scanner>



Front View



Left Side View




Right Side View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Report Issued Date: Aug. 14, 2013

Report Version : Rev. 01



<Battery 2 with Scanner>



Front View



Left Side View



Right Side View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Report Issued Date: Aug. 14, 2013

Report No.: HA322304-07A

Report Version : Rev. 01