


Appendix B. Setup Photographs


<Radiated Emission>

<H Plane>

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET1N2 Page Number : B1 of B3
Report Issued Date : Jun. 19, 2012
Report Version : Rev. 01

Report No.: FG252422







Report No. : FG252422

<E1 Plane>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET1N2 Page Number : B2 of B3
Report Issued Date : Jun. 19, 2012
Report Version : Rev. 01





<E2 Plane>

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET1N2 Page Number : B3 of B3
Report Issued Date : Jun. 19, 2012
Report Version : Rev. 01

Report No.: FG252422