

Appendix D. SAR Test Setup Photos <With Scanner>



Right Cheek With Battery 1



Right Cheek With Battery 2



Right Tilted With Battery 1



Left Cheek With Battery 1



Left Tilted With Battery 1

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number : D1 of D4 Report Issued Date: Feb. 10, 2014

Report Version : Rev. 01








Bottom Side With Battery 1,Test Separation 1 cm


Top Side With Battery 1, Test Separation 1 cm








Right Side With Battery 1,Test Separation 1 cm








Back With Battery 1,Test Separation 1 cm

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number : D2 of D4 Report Issued Date: Feb. 10, 2014 Report Version : Rev. 01




Back With Battery 2, Test Separation 1 cm




Back With Battery 1 and Holster,
Test Separation 0 cm



Back With Battery 1, Test Separation 1.5 cm



Back With Battery 2, Test Separation 1.5 cm



Back With Battery 1 and Headset, Test Separation 1.5 cm

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number : D3 of D4
Report Issued Date : Feb. 10, 2014
Report Version : Rev. 01



<Without Scanner>



Right Cheek With Battery 1







Back With Battery 1, Test Separation 1.5 cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number : D4 of D4
Report Issued Date : Feb. 10, 2014

Report Version : Rev. 01