#### **Report No. : FR270520**

**Appendix A. Test Photos** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01

# 1 Photographs of Conducted Emissions Test Configuration

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01




#### **REAR VIEW**


SPORTON INTERNATIONAL INC. Page No. : A3 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01

# 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01

For radiated emissions 30MHz~1GHz

**Transmit Mode** 



#### **FRONT VIEW**



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A5 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01

#### For radiated emissions above 1GHz

**Transmit Mode** 



#### **FRONT VIEW**



## **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No. : A6 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01

EUT with speaker nugget



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A7 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01

# EUT with headset nugget



#### **FRONT VIEW**



### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No. : A8 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01