


# Appendix A. Setup Photographs

## <Conducted Emission>

Mode 1

<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A1 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A2 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2



Mode 1
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A3 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2





Report No.: FR672834D

Rear View



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A4 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03



Mode 2
<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A5 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834D







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A6 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2



Mode 2
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A7 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2








SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A8 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report No.: FR672834D



Mode 3
<Original test result with NFC antenna>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A9 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A10 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03



# Mode 3 <Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A11 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A12 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03

Report Template No.: BU5-FR15CNFC Version 1.2




Report No.: FR672834D


### <Radiated Emission>

#### **Z** Plane

#### From 9kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : A13 of A13
Report Issued Date : Oct. 07, 2016
Report Version : Rev. 03