

# Appendix A. Setup Photographs

# <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : A1 of A4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01

Report No.: FR573017D



Report No.: FR573017D


## <Radiated Emission>

#### <Sample 1>

#### 9 kHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : A2 of A4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01




Report No.: FR573017D

# <Sample 2>

#### 9 kHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : A3 of A4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01




Report No.: FR573017D

## <Sample 3>

#### 9 kHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC80NH Page Number : A4 of A4
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01