## **Appendix B. Test Results of Radiated Test**

## **ERP/EIRP**

	Cellular Band (G <sub>T</sub> - L <sub>C</sub> = 1.00 dB)									
Modes	WCDMA Band V (RMC 12.2Kbps)									
Channel	4132 (Low)	4132 (Low) 4182(Mid) 4233 (High)								
Frequency (MHz)	826.4	836.4	846.6							
Conducted Power (dBm)	22.69	22.46	22.8							
Conducted Power (Watts)	0.19	0.18	0.19							
EIRP(dBm)	21.54	21.31	21.65							
EIRP(Watts)	0.1426	0.1352	0.1462							

PCS Band (G <sub>T</sub> - L <sub>C</sub> = 2.00 dB)										
Modes	WCDMA Band II (RMC 12.2Kbps)									
Channel	9262 (Low)	9262 (Low) 9400 (Mid) 9538 (High)								
Frequency (MHz)	1852.4	1880	1907.6							
Conducted Power (dBm)	22.53	22.56	22.06							
Conducted Power (Watts)	0.18	0.18	0.16							
EIRP(dBm)	24.53	24.56	24.06							
EIRP(Watts)	0.2838	0.2858	0.2547							

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : B1 of B5
Report Issued Date : Nov. 20, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1

	AWS Band ( $G_T - L_C = 2.00 \text{ dB}$ )								
Modes	WCDMA Band IV (RMC 12.2Kbps)								
Channel	1312 (Low)	1312 (Low) 1413 (Mid) 1513 (High)							
Frequency (MHz)	1712.4	1732.6	1752.6						
Conducted Power (dBm)	22.4	22.36	22.85						
Conducted Power (Watts)	0.17	0.17	0.19						
EIRP(dBm)	24.4	24.36	24.85						
EIRP(Watts)	0.2754	0.2729	0.3055						

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : B2 of B5
Report Issued Date : Nov. 20, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1

## Radiated Spurious Emission

	WCDMA Band V(RMC 12.2Kbps)									
Channel	Frequency ( MHz )	ERP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power (dBm)	TX Cable loss (dB)	TX Antenna Gain (dBi)	Polarization (H/V)	
	1656	-56.69	-13	-43.69	-65.18	-58.42	0.98	4.86	Н	
	2488	-63.08	-13	-50.08	-75.16	-65.01	1.29	5.36	Н	
Lowest	3312	-60.18	-13	-47.18	-75.63	-63.66	1.55	7.17	Н	
Lowest	1656	-59.10	-13	-46.10	-65.51	-60.83	0.98	4.86	V	
	2484	-60.57	-13	-47.57	-74.81	-62.49	1.29	5.35	V	
	3312	-60.90	-13	-47.90	-75.28	-64.38	1.55	7.17	V	
	1672	-51.37	-13	-38.37	-60.74	-53.05	0.99	4.82	Н	
	2512	-61.29	-13	-48.29	-74.56	-63.26	1.29	5.41	Н	
Mi al all a	3344	-59.01	-13	-46.01	-75.43	-62.62	1.56	7.31	Н	
Middle	1672	-53.78	-13	-40.78	-61.17	-55.46	0.99	4.82	V	
	2512	-59.24	-13	-46.24	-74.65	-61.21	1.29	5.41	V	
	3344	-60.39	-13	-47.39	-75.57	-64	1.56	7.31	V	
	1696	-52.52	-13	-39.52	-62	-54.12	1.00	4.75	Н	
Highest	2544	-61.11	-13	-48.11	-74.83	-63.09	1.30	5.44	Н	
	3392	-59.07	-13	-46.07	-75.46	-62.87	1.57	7.52	Н	
	1696	-54.89	-13	-41.89	-62.67	-56.49	1.00	4.75	V	
	2544	-59.13	-13	-46.13	-74.5	-61.11	1.30	5.44	V	
	3392	-59.64	-13	-46.64	-75.63	-63.44	1.57	7.52	V	

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : B3 of B5
Report Issued Date : Nov. 20, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1

	WCDMA Band II(RMC 12.2Kbps)										
Channel	Frequency (MHz)	EIRP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power (dBm)	TX Cable loss ( dB )	TX Antenna Gain (dBi)	Polarization (H/V)		
	3707	-50.91	-13	-37.91	-68.56	-57.49	1.67	8.25	Н		
	5562	-54.33	-13	-41.33	-77	-61.39	2.66	9.72	Н		
Lowest	7417	-48.64	-13	-35.64	-76.38	-57.82	2.46	11.63	Н		
Lowest	3707	-46.12	-13	-33.12	-63.66	-52.7	1.67	8.25	V		
	5562	-55.78	-13	-42.78	-76.91	-62.84	2.66	9.72	V		
	7417	-49.53	-13	-36.53	-76.58	-58.71	2.46	11.63	V		
	3756	-51.37	-13	-38.37	-69.39	-57.99	1.68	8.31	Н		
	5634	-54.52	-13	-41.52	-77.24	-61.57	2.70	9.75	Н		
Middle	7515	-48.67	-13	-35.67	-76.38	-58.05	2.42	11.81	Н		
Middle	3756	-46.82	-13	-33.82	-64.44	-53.44	1.68	8.31	V		
	5634	-55.86	-13	-42.86	-76.95	-62.91	2.70	9.75	V		
	7515	-49.26	-13	-36.26	-76.6	-58.64	2.42	11.81	V		
	3819	-50.01	-13	-37.01	-68.6	-56.69	1.70	8.38	Н		
	5728.5	-54.09	-13	-41.09	-77.21	-61.12	2.76	9.79	Н		
Highest	7641	-49.35	-13	-36.35	-76.76	-58.85	2.38	11.88	Н		
	3819	-46.45	-13	-33.45	-64.14	-53.13	1.70	8.38	V		
	5730	-54.79	-13	-41.79	-76.93	-61.82	2.76	9.79	V		
	7641	-49.95	-13	-36.95	-76.89	-59.45	2.38	11.88	V		

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : B4 of B5
Report Issued Date : Nov. 20, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1

	WCDMA Band IV(RMC 12.2Kbps)									
Channel	Frequency ( MHz )	EIRP (dBm)	Limit ( dBm )	Over Limit ( dB )	SPA Reading (dBm)	S.G. Power (dBm)	TX Cable loss (dB)	TX Antenna Gain (dBi)	Polarization (H/V)	
	3427	-59.27	-13	-46.27	-74.97	-65.37	1.58	7.68	Н	
	5142	-54.57	-13	-41.57	-76.32	-61.85	2.42	9.70	Н	
Lowest	6857	-51.09	-13	-38.09	-77.06	-59.08	2.64	10.63	Н	
Lowest	3427	-55.35	-13	-42.35	-70.73	-61.45	1.58	7.68	V	
	5142	-55.61	-13	-42.61	-76.61	-62.89	2.42	9.70	V	
	6857	-51.43	-13	-38.43	-77.06	-59.42	2.64	10.63	V	
	3462	-57.42	-13	-44.42	-73.41	-63.66	1.59	7.83	Н	
	5191	-55.12	-13	-42.12	-76.84	-62.37	2.45	9.70	Н	
Middle	6927	-50.63	-13	-37.63	-76.87	-58.73	2.61	10.71	Н	
Middle	3462	-54.28	-13	-41.28	-70.19	-60.52	1.59	7.83	V	
	5191	-55.11	-13	-42.11	-76.33	-62.36	2.45	9.70	V	
	6927	-50.76	-13	-37.76	-76.79	-58.86	2.61	10.71	V	
	3504	-58.10	-13	-45.10	-74.37	-64.5	1.61	8.00	Н	
	5254	-55.22	-13	-42.22	-76.86	-62.44	2.48	9.70	Н	
Highest	7011	-50.20	-13	-37.20	-76.76	-58.44	2.59	10.82	Н	
	3504	-55.21	-13	-42.21	-71.64	-61.61	1.61	8.00	V	
	5254	-55.12	-13	-42.12	-77.03	-62.34	2.48	9.70	V	
	7011	-50.12	-13	-37.12	-76.67	-58.36	2.59	10.82	V	

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : B5 of B5
Report Issued Date : Nov. 20, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1