

Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : A1 of A2
Report Issued Date : Apr. 11, 2014
Report Version : Rev. 01

Report No.: FR421184


Report Template No.: BU5-FR15CWL Version 1.0




Report No.: FR421184

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : A2 of A2
Report Issued Date : Apr. 11, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0