


Report No.: FR5N0203

## Appendix A. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : A1 of A2
Report Issued Date : Nov. 23, 2015
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.0




Report No.: FR5N0203

## <Radiated Emission>

LF



HF



## SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K888 Page Number : A2 of A2
Report Issued Date : Nov. 23, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0