


**Appendix D. Duty Cycle Plots** 

Antenna	Band	Duty Cycle(%)	T(us)	1/T(kHz)	VBW Setting
1	802.11b	100	-	-	10Hz
2	802.11b	100	-	-	10Hz
1+2	802.11b for Ant 1	100	-	-	10Hz
1+2	802.11b for Ant 2	100	-	-	10Hz
1	802.11g	95.775	1360	0.74	1kHz
2	802.11g	95.775	1360	0.74	1kHz
1+2	802.11g for Ant 1	95.714	1340	0.75	1kHz
1+2	802.11g for Ant 2	95.774	1360	0.74	1kHz
1	2.4GHz 802.11n HT20	95.455	1260	0.79	1kHz
2	2.4GHz 802.11n HT20	95.455	1260	0.79	1kHz
1+2	2.4GHz 802.11n HT20 for Ant 1	95.489	1270	0.79	1kHz
1+2	2.4GHz 802.11n HT20 for Ant 2	96.241	1280	0.78	1kHz
1	2.4GHz 802.11n HT40	94.048	632	1.58	3kHz
2	2.4GHz 802.11n HT40	93.452	628	1.59	3kHz
1+2	2.4GHz 802.11n HT40 for Ant 1	93.491	632	1.58	3kHz
1+2	2.4GHz 802.11n HT40 for Ant 2	94.048	632	1.58	3kHz

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Report No.: FR6O0520




<Ant. 1> 802.11b



Date: 7.OCT.2016 10:25:30

## 802.11g




Date: 7.OCT.2016 11:08:34

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number


: D2 of D9





Date: 7.OCT.2016 11:27:04

### 802.11n HT40



Date: 7.OCT.2016 13:35:58


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: D3 of D9




<Ant. 2> 802.11b



Date: 7.OCT.2016 10:29:57

### 802.11g



Date: 7.OCT.2016 11:01:58


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: D4 of D9




#### 802.11n HT20



Date: 7.OCT.2016 11:27:49

### 802.11n HT40



Date: 7.OCT.2016 13:36:33

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: D5 of D9






# MIMO <Ant. 1+2(1)> 802.11b



Date: 7.OCT.2016 10:16:56

## 802.11g



Date: 7.OCT.2016 11:02:57


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: D6 of D9




#### 802.11n HT20



Date: 7.OCT.2016 11:28:38

### 802.11n HT40



Date: 7.OCT.2016 13:34:43


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978






# MIMO <Ant. 1+2(2)> 802.11b



Date: 7.OCT.2016 10:17:24

### 802.11g



Date: 7.OCT.2016 11:03:25


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: D8 of D9








Date: 7.OCT.2016 11:29:21

### 802.11n HT40



Date: 7.OCT.2016 13:35:27

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: D9 of D9