

Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-565R66 Page Number : A1 of A2
Report Issued Date : Jun. 17, 2014
Report Version : Rev. 01


Report No.: FR451961

Report Template No.: BU5-FR15CWL Version 1.0




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-565R66 Page Number : A2 of A2
Report Issued Date : Jun. 17, 2014
Report Version : Rev. 01

Report No.: FR451961

Report Template No.: BU5-FR15CWL Version 1.0