3. Internal Photograph of EUT


Brand Name: BandLuxe / Model Name: K535U

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 11 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 12 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 13 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 14 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 15 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 16 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 17 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01


Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 18 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01




Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 19 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 20 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 21 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01


Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 22 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01




Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 23 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 24 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 25 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01


Report No.: EP421184




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 26 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01


Report No.: EP421184

Brand Name: BandLuxe / Model Name: K535U




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 27 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 28 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 29 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01

Report No.: EP421184



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-35K899 Page Number : 30 of 30
Report Issued Date : Apr. 09, 2014
Report Version : Rev. 01