


Report File No. : F690501/RF-RTL001571
Page : 19 of 23

Inner of EUT



Top View of Main-board (Can't remove Shield Cap)



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.




Report File No. : F690501/RF-RTL001571
Page : 20 of 23

Bottom View of Main-board



Top View of Sub-board




The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.




Report File No. : F690501/RF-RTL001571
Page : 21 of 23

Bottom View of Sub-board



Top View of Sub-board




The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.



Report File No. : F690501/RF-RTL001571
Page : 22 of 23

Bottom View of Sub-board



Top View of Board-Lens





Report File No. : F690501/RF-RTL001571
Page : 23 of 23

Bottom of Board-Lens

