
Internal photographs of equipment under test

Transmitter board placed on the support interface board



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Wilibox Deliberant Grp FCC ID#: V2U-WMR500 Model: WMR500 IC: 7606A-WMR500

Test #: 080119

Test to: FCC Parts 2 and 15c File: IntPho WMR500

Page 1 of 3 Date: March 24, 2008

Top of Transmitter module without shield in place



Bottom side of Transmitter module



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Wilibox Deliberant Grp FCC ID#: V2U-WMR500 Model: WMR500 IC: 7606A-WMR500

Test #: 080119

Test to: FCC Parts 2 and 15c File: IntPho WMR500

Page 2 of 3 Date: March 24, 2008

Support interface board





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Wilibox Deliberant Grp FCC ID#: V2U-WMR500 Model: WMR500 IC: 7606A-WMR500

Test #: 080119

Test to: FCC Parts 2 and 15c Page 3 of 3
File: IntPho WMR500 Date: March 24, 2008