
FCC TEST REPORT Report No.:FR820108

APPENDIX B. Photographs of EUT






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : **B**1 OF **B8**ISSUED DATE : Feb. 17, 2008


FCC TEST REPORT





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : **B**2 OF **B8**ISSUED DATE : Feb. 17, 2008


FCC TEST REPORT





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC TEST REPORT Report No.:FR820108





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : **B**6 OF **B8**ISSUED DATE : Feb. 17, 2008