


FCC Test Report Report No.: FR5N2626AC

Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration

Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



CC Test Report No.: FR5N2626AC



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



FCC Test Report Report No.: FR5N2626AC

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A6 Report Version : Rev. 01



FCC Test Report No.: FR5N2626AC

For radiated emissions 30MHz~1GHz

Mode 2



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6 Report Version : Rev. 01




FCC Test Report No.: FR5N2626AC

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





Report No. : FR5N2626AC



EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6 Report Version : Rev. 01