YISO Wireless Co., Ltd., FCC ID: V4NM893, Assessment NO.: AN08T7742, Notice#1

Inbox



hide details Mar 27 (11 days ago) Reply Reply

- klmnb2002@e-ctk.com,
- tim.dwyer@ccsemc.com. lucy.tsai@ccsemc.com,
- date Thu, Mar 27, 2008 at 4:25 PM
- subject YISO Wireless Co., Ltd., FCC ID: V4NM893, Assessment NO.: AN08T7742, Notice#1

Dear Shin Kyu Chul,

Review of this application is complete. Please reply to the following items. If you have questions, please ask and I will try to explain.

- Q1: Test setup photos show only radiated setup. Please provide test setup photos to include conducted setups.
- Q2: No power line conducted or radiated emissions test data < 1GHz is included in the test report as referenced in 3.1.7 and 3.1.8. As this device is considered a "peripheral device" according to FCC rules, and the FCC Declaration of Conformity labeling is used, please confirm that this device has been shown to comply with the requirements of FCC Part 15 for power line conducted and radiated emissions using the Declaration of Conformity procedure.
- Q3: Antenna specifications were not included in the filing. Please provide an antenna specification exhibit for the antenna used for the measurements.
- Q4: The ERP and EIRP values and antenna gains used for MPE calculations on pages 78 and 79 of the test report do not agree with results reported on pages 9-11. Please provide revised data or additional explanation in the MPE calculations.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer Technical Reviewer

Reply Reply to all Forward


to tim.dwyer

show details Apr 1 (7 days ago) Reply Reply



- Q1: Test setup photos show only radiated setup. Please provide test setup photos to include conducted setups. >Attach setup photo
- > Q2: No power line conducted or radiated emissions test data < 1GHz is included in the test report as referenced in 3.1.7 and 3.1.8. As this device is considered a "peripheral device" according to FCC rules, and the FCC Declaration of Conformity labeling is used, please confirm that this device has been shown to comply with the requirements of FCC Part 15 for power line conducted and radiated emissions using the Declaration of Conformity procedure. > Attach labeling
- > Q3: Antenna specifications were not included in the filing. Please provide an antenna specification exhibit for the antenna used for the measurements.
- > Attach antenna specification
- > Q4: The ERP and EIRP values and antenna gains used for MPE calculations on pages 78 and 79 of the test report do not agree with results reported on pages 9-11. Please provide revised data or additional explanation in the MPE calculations.
- > Sorry Test mistake Test again and attaches atresults
- > Best regards,
- Show quoted text -


4 attachments — Download all attachments



I do not understand

This device is CDMA modeule, By the way, why are this devices a peripheral device?

Attaches eut photo and Test zig Need not this devices to do doc? Best regards Thanks - Show quoted text -2 attachments — <u>Download all attachments</u> eut photo.pdf 115K View as HTML Download [M893] Label and Location.pdf 142K View as HTML Download Reply Forward hide details Apr 3 (5 days ago) Reply from **Tim Dwyer** <Timothy_Dwyer@ieee.org> <klmnb2002@e-ctk.com>, to Mike Kuo <mike.kuo@ccsemc.com>, Thu, Apr 3, 2008 at 11:52 AM Re: YISO Wireless Co., Ltd., FCC ID: V4NM893, Assessment NO.: AN08T7742, Notice#1 subject mailed-by gmail.com Hi Shin Kyu Chul, Current FCC policy includes this type of product in definition for "peripheral device". The definition for "peripheral device" is in FCC Part 15, clause 15.3(r). FCC has recently dismissed a number of grants because they did not include information about compliance for the composite peripheral device. So to complete this application, we need your statement that it complies using the DoC procedure, or a separate composite JBP application for certification can be submitted. Best regards, Tim Dwyer Technical Reviewer 2008/4/1 <klmnb2002@e-ctk.com>: - Show quoted text -Reply Reply to all Forward



hide details Apr 5 (3 days ago) Reply ## from <klmnb2002@e-ctk.com> to Tim Dwyer <Timothy_Dwyer@ieee.org>, Sat, Apr 5, 2008 at 12:30 AM date subject Re: YISO Wireless Co., Ltd., FCC ID: V4NM893, Assessment NO.: AN08T7742, Notice#1 Hi Tim Dwyer Attaches FCC Part 15 DoC Best regards Thank ---- Original Message -----From: <u>Tim Dwyer</u> To: ______ - Show quoted text -[M893] FCC DoC.pdf 235K View as HTML Download