

Units 4107-10, 41/F, Manhattan Place, 23 Wang Tai Road, Kowloon Bay, Kowloon, Hong Kong.

Tel: +852 34233331 Fax: +852 27961286

Email: elsie@acs.com.hk

2017/12/05

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

## **Attestation Letter**

Dear Sir or Madam:

The RF chip, model MAX32590, which installed in our product Banking POS Terminal, model: ACR900 , FCC ID: V5MACR900, supports BT functions. For use in the USA this chip will not support/enable the BT function. The BT function has been shielded by the manufacturer using the software.

Sincerely,

Signature: Alie fai

Elsie Lai

Executive Vice President, Product Marketing