


#### Report No.: FR642904B

# Appendix D. Setup Photographs

## <Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX7W Page Number : D1 of D2
Report Issued Date : Aug. 19, 2016
Report Version : Rev. 01




## Report No.: FR642904B

### <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: V5PPX7W Page Number : D2 of D2
Report Issued Date : Aug. 19, 2016
Report Version : Rev. 01