
## 3. Internal Photograph of EUT

Brand Name: PAX; Model Name: D180; Marketing Name: D180

Report No.: EP450402




TEL: 86-755- 3320-2398 FCC ID: V5PD180BT

Page Number : 10 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01




Report No.: EP450402



TEL: 86-755-3320-2398 FCC ID: V5PD180BT


Page Number : 11 of 27 Report Issued Date : Jun. 11, 2014 Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD180BT

Page Number : 12 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: V5PD180BT


Page Number : 13 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: V5PD180BT

Page Number : 14 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: V5PD180BT

Page Number : 15 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01

Report No.: EP450402




TEL: 86-755- 3320-2398 FCC ID: V5PD180BT

Page Number : 16 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01




Report No.: EP450402



TEL: 86-755-3320-2398 FCC ID: V5PD180BT

Page Number : 17 of 27 Report Issued Date : Jun. 11, 2014 Report Version : Rev. 01

Report No.: EP450402




TEL: 86-755-3320-2398 FCC ID: V5PD180BT

Page Number : 18 of 27 Report Issued Date : Jun. 11, 2014 Report Version : Rev. 01



Report No.: EP450402




TEL: 86-755-3320-2398 FCC ID: V5PD180BT

Page Number : 19 of 27 Report Issued Date : Jun. 11, 2014 Report Version : Rev. 01




Report No.: EP450402




TEL: 86-755-3320-2398 FCC ID: V5PD180BT

Page Number : 20 of 27 Report Issued Date : Jun. 11, 2014 Report Version : Rev. 01




TEL: 86-755- 3320-2398 FCC ID: V5PD180BT Page Number : 21 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01





TEL: 86-755- 3320-2398 FCC ID: V5PD180BT


Page Number : 22 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: V5PD180BT


Page Number : 23 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01

Report No.: EP450402




TEL: 86-755- 3320-2398 FCC ID: V5PD180BT Page Number : 24 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01

Report No.: EP450402




TEL: 86-755- 3320-2398 FCC ID: V5PD180BT Page Number : 25 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01

Report No.: EP450402



TEL: 86-755- 3320-2398 FCC ID: V5PD180BT Page Number : 26 of 27
Report Issued Date : Jun. 11, 2014
Report Version : Rev. 01

Report No.: EP450402



TEL: 86-755-3320-2398 FCC ID: V5PD180BT

Page Number : 27 of 27 Report Issued Date : Jun. 11, 2014 Report Version : Rev. 01